

Test Report

Number: GZHH00640623

Applicant:



Date: Jun 30, 2026

Attn: HILL YU

Sample Description:

One (1) piece of submitted sample said to be :

Item Name : c Reclined Cradle and Bouncer

Item No. :

Manufacturer :

Country of Destination :

Country of Origin :

Date Sample Received : Apr 07, 2026 & Apr 24, 2026 & Jun 17, 2026

Testing Period : Apr 07, 2026 to Jun 29, 2026



Tests conducted:

As requested by the applicant, refer to attached page(s) for details.

To be continued



Page 1 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00640623

Conclusion:

Tested samples
Submitted sample

Standard

Child Care Articles – Reclined Cradles – Part 1: Reclined cradles for children up to when they start to try to sit up
- EN 12790-1: 2023

(Excluding:

- Clause 6.2: Migration of certain elements
- Clause 6.3: Formaldehyde
- Clause 6.4: Colourants
- Clause 6.5: Aniline
- Clause 7: Thermal hazards)

Result

Pass
(See remark)

Child Care Articles – Reclined Cradles – Part 2: Reclined cradles for children up to when they start to stand up
- EN 12790-2: 2023


Pass
(See remark)

Remark :

1. Only artwork of product information was provided for review, the permanence & graphical symbols dimension of label and the height of the words in the warning statements were not assessed in this report.

Authorized by:

For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch, Hardlines



Victor T.J. Wang
General Manager



Should you have any query on this report, please click the link below:
https://verifyindex.intertek.com.cn/home/index?id=hl_report_verify



Page 2 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00640623

Tests Conducted

1 Safety Requirements and Test Methods for Reclined Cradles

As per EN 12790-1: 2023 – Child Care Articles – Reclined Cradles – Part 1: Reclined cradles for children up to when they start to try to sit up, the following tests were conducted on the submitted sample.

Executive summary :

Clause	Testing items	Result
1	Scope	
2	Normative references	
3	Terms and definitions	
4	Test equipment	
5	General requirements and test conditions	
6	Chemical hazards	
6.1	General	
6.2	Migration of certain elements	NR
6.3	Formaldehyde	NR
6.4	Colourants	NR
6.5	Aniline	NR
7	Thermal hazards	NR
8	Mechanical hazards	
8.1	General	
8.2	Hazards due to sound level	P
8.3	Entrapment hazards	P
8.4	Hazards due to moving parts	P
8.5	Hazards due to falling of the child	
8.5.1	Angle of seat unit	P
8.5.2	Restraint system	P
8.5.3	Locking mechanism(s) for carrying handle(s)	NA
8.6	Hazards due to folding of the product	P
8.7	Hazards from entanglement in cords, ribbons and similar parts	NA
8.8	Choking and ingestion hazard	P
8.9	Suffocation hazards from plastic packaging	NA
8.10	Hazards from edges, corners and protruding parts	P
8.11	Hazards from inadequate structural integrity	
8.11.1	Static strength	P
8.11.2	Dynamic strength	P
8.11.3	Reclining system	P
8.11.4	Durability of powered mechanisms	P
8.11.5	Durability of reclined cradles with carrying handle(s)	NA
8.11.6	Strength of carry handle(s) locking mechanism(s)	NA
8.11.7	Toy bar attachment integrity	P



Page 3 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、

601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com


Test Report

Number: GZHH00640623

Tests Conducted

Clause	Testing items	Result
8.12	Hazards from inadequate stability	P
8.13	Hazards from possible slippage of the reclined cradle	P
8.14	Electrical hazards	
8.14.1	General	P
8.14.2	Leakage prevention	NA
9	Product information	
9.1	General	P (See remark 1)
9.2	Marking of the product	P (See remark 1)
9.3	Purchase information	P (See remark 1)
9.4	Instruction for use	P (See remark 1)

Abbreviation : P = Pass; NA = Not applicable; NR = Not requested by the applicant

2 Safety Requirements and Test Methods Reclined Cradles

As per EN 12790-2: 2023 – Child Care Articles – Reclined Cradles – Part 2: Reclined cradles for children up to when they start to stand up, the following tests were conducted on the submitted sample.

Executive summary :

Clause	Testing items	Result
1	Scope	
2	Normative references	
3	Terms and definitions	
4	General requirements and test conditions	
4.1	General requirements (compliance of in conjunction with and in addition to EN 12790-1:2023)	P
4.2	Test conditions	
5	Test equipment	
6	Mechanical hazards	
6.1	Forward stability	P
6.2	Static strength	P
6.3	Dynamic strength	P
6.4	Reclining system	P
6.5	Hazards from possible slippage of the reclined cradle	P



Page 4 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com


Test Report

Number: GZHH00640623

Tests Conducted

Clause	Testing items	Result
7	Product information	
7.1	General	P (See remark 1)
7.2	Marking of the product	P (See remark 1)
7.3	Purchase information	P (See remark 1)
7.4	Instruction for use	P (See remark 1)

Abbreviation : P = Pass.

End of report

The statements of conformity reported have considered the decision rule agreed, namely that Intertek have taken account of measurement uncertainty as calculated by Intertek, and applied according to ILAC-G8/09:2019 (Non-binary acceptance based on guard band $w = U$) except designation from the customer, regulation or test specification. This decision rule only applies to the numeric test results.

The sample(s) and sample information hereto are provided by the client who shall be solely responsible for the authenticity and integrity thereof. The results shown in this report relate only to the sample(s) tested. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. This report shall not be reproduced unless with prior written approval from Intertek Testing Services Shenzhen Limited, Guangzhou Branch.



Page 5 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com

