

Test Report

Number: GZHH00634036

Applicant:



Date: Apr 03, 2026

Attn: HILL YU

Sample Description:

One (1) piece of submitted sample said to be :

Item Name	:	Electric Swing and Music Bouncer
Item No.	:	
Manufacturer	:	
Country of Destination	:	
Country of Origin	:	China
Date Sample Received	:	Feb 03, 2026 & Mar 11, 2026
Testing Period	:	Feb 03, 2026 to Apr 03, 2026



Tests conducted:

As requested by the applicant, refer to attached page(s) for details.

To be continued



Page 1 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00634036

Conclusion:

Tested samples
Submitted sample

Standard/Test Item

ASTM F2088-25 - Standard Consumer Safety
Specification for Infant and Cradle Swings

Excluding:

- Clause 5.3: Paint and surface coating
- Clause 5.9: Labeling
- Clause 5.10: Toys
- Clause 6.1: Electrically powered swings

Result

Pass
(See remark)

16 CFR 1223 (Incorporating by reference ASTM
F2088-24)

- Safety Standard for Infant Swings

Excluding:

- Clause 5.3: Paint and surface coating
- Clause 5.9: Labeling
- Clause 5.10: Toys
- Clause 6.1: Electrically powered swings

Pass


(See remark)

Remark:

1. Only artwork of labeling, package & instruction was provided for review, the permanence & the position of the labeling and the height of warning information was not assessed in this report.

Authorized by:

For Intertek Testing Services Shenzhen Ltd.
Guangzhou Branch, Hardlines



Victor T.J. Wang
General Manager



Should you have any query on this report, please click the link below:
https://verifyindex.intertek.com.cn/home/index?id=hl_report_verify



Page 2 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District,
Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road,
Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、
601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com



Test Report

Number: GZHH00634036

Tests Conducted

1 Safety Specification for Infant and Cradle Swings

Reference standard: ASTM F2088-25 - Standard Consumer Safety Specification for Infant and Cradle Swings.

Executive summary:

Clause	Testing items	Result
1	Scope	
2	Referenced documents	
3	Terminology	
4	Calibration and standardization	
5	General requirements	
5.1	Hazardous sharp edges or points (16 CFR 1500.49 or 16 CFR 1500.48)	P
5.2	Small parts (16 CFR 1501)	P
5.3	Paint and surface coating (16 CFR 1303)	NR
5.4	Wood parts	NA
5.5	Scissoring, shearing, pinching	P
5.6	Openings	P
5.7	Exposed coil springs	NA
5.8	Protective components	P
5.9	Labeling	NR
5.10	Toys (ASTM F963)	NR
5.11	Cradle swings or combination swings in a cradle swing use, mode, or position	NA
6	Performance requirements	
6.1	Electrically powered swings	
6.1.1	Battery leakage	NR
6.1.2	Protection against charging non-rechargeable battery	NR
6.1.3	Temperatures of the surfaces of accessible electrical component	NR
6.1.4	AC adapters	NR
6.2	Structural integrity	
6.2.1	Dynamic load	P
6.2.2	Static load	P
6.3	Stability test	P
6.4	Unintentional folding	P
6.5	Restraint system	P
6.6	Passive crotch restraint system	NA



Page 3 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com


Test Report

Number: GZHH00634036

Tests Conducted

Clause	Testing items	Result
6.7	Cradle swing orientation	NA
6.8	Seat angles for swings with removable tray/armbar or without tray/armbar	P
6.9	Tethered strap or cord entrapment or entanglement accessibility for non-occupants	P
7	Test methods	
8	Marking and labeling	P (See remark 1)
9	Instructional literature	P (See remark 1)

Abbreviation : P = Pass; NA = Not applicable; NR = Not requested by the applicant

2 Safety Standard for Infant Swings

As per 16 CFR 1223 – Safety Standard for Infant Swings, the submitted sample was subjected to the following tests in accordance with the variations of ASTM F2088-24.

Executive summary:

Clause	Testing Items	Result
1	Scope	
2	Referenced documents	
3	Terminology	
4	Calibration and standardization	
5	General requirements	
5.1	Hazardous sharp edges or points (16 CFR 1500.49 or 16 CFR 1500.48)	P
5.2	Small parts	P
5.3	Paint and surface coating	NR
5.4	Wood parts	NA
5.5	Scissoring, shearing, pinching	P
5.6	Openings	P
5.7	Exposed coil springs	NA
5.8	Protective components	P
5.9	Labeling	NR
5.10	Toys (ASTM F963)	NR
5.11	Cradle swings or combination swings in a cradle swing use, mode, or position	NA
6	Performance requirements	
6.1	Electrically powered swings	
6.1.1	Battery leakage	NR
6.1.2	Protection against charging non-rechargeable battery	NR
6.1.3	Temperatures of the surfaces of accessible electrical component	NR
6.1.4	AC adapters	NR
6.2	Structural integrity	
6.2.1	Dynamic load	P
6.2.2	Static load	P
6.3	Stability test	P
6.4	Unintentional folding	P
6.5	Restraint system	P
6.6	Passive crotch restraint system	NA
6.7	Cradle swing orientation	NA



Page 4 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、

601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com


Test Report

Number: GZHH00634036

Tests Conducted

Clause	Testing Items	Result
6.8	Seat angles for swings with removable tray/armbar or without tray/armbar	P
6.9	Tethered strap or cord entrapment or entanglement accessibility for non-occupants	P
7	Test methods	
8	Marking and labeling	P (See remark 1)
9	Instructional literature	P (See remark 1)

Abbreviation : P = Pass; NA = Not applicable; NR = Not requested by the applicant

End of report

The statements of conformity reported have considered the decision rule agreed, namely that Intertek have taken account of measurement uncertainty as calculated by Intertek, and applied according to ILAC-G8/09:2019 (Non-binary acceptance based on guard band $w = U$) except designation from the customer, regulation or test specification. This decision rule only applies to the numeric test results.

The sample(s) and sample information hereto are provided by the client who shall be solely responsible for the authenticity and integrity thereof. The results shown in this report relate only to the sample(s) tested. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. This report shall not be reproduced unless with prior written approval from Intertek Testing Services Shenzhen Limited, Guangzhou Branch.



Page 5 of 5

Intertek Testing Services Shenzhen Limited, Guangzhou Branch

深圳天祥质量技术服务有限公司广州分公司

111, Huichuang Kongjian, TCL Cultural Industrial Park, No.69, Guangpu Road, Huangpu District, Guangzhou, Guangdong, China. / Room 401/501/601/801/901/1003, No. 8, East BaoYing Road, Huangpu District, Guangzhou, China

广州市黄埔区光谱西路 69 号 TCL 文化产业园汇创空间 111 室/广州市黄埔区保盈东路 8 号 401 房、501 房、

601 房、801 房、901 房、1003 房

Tel +8620 28209114
intertek.com.cn
intertek.com

