

**SÜNGER KALİTE KONTROL
TEST RAPORU**
Yayın Tarihi: 02.01.2014

SÜNGER CİNSİ :10 PPI Ü.D. Retiküle (Ant_Re.Yeşil_Re.Mavi) Sünger
DANSİTE :22
PARTİ NO :0608203221
İMALAT TARİHİ :06.08.2020

FİZİKSEL ÖZELLİKLER	KULLANILAN STANDART	ÜROSAN STANDARDI	TEST SONUCU
DANSİTE (kg/m ³)	ISO 845	22(-/+2)	20,59
SERTLİK (ILD %40) (N)	ISO 2439	165 ± %15	161,79
ÇEKME MUKAVEMETİ (kPa)	ISO 1798	≥ 60	92,58
KOPMA UZAMASI (%)	ISO 1798	≥ 40	65,3
YIRTILMA MUKAVEMETİ (N/cm)	ASTM. D 3574	≥ 4	6,09
GÖZ SAYISI (adet/inç)	ÜK K03 T10	10(-/+3)	10
HAVA GEÇİRGENLİĞİ(dm3/s/dk)	ISO7231	≥6	8,31



**TS EN ISO 9001:2015
999-01**

FABRİKA ADRES : Velimeşe OSB Mah. 128. Sok. No: 9/1
59930 Ergene /Tekirdağ

MERKEZ ADRES : Kavacık Mah. Ekinçiler Cad. No:24
Eren Plaza K: 5
34810Beykoz/İSTANBUL

FABRİKA TEL : (0282) 674 40 50
FABRİKA FAX : (0282) 674 40 51

MERKEZ TEL : (0216) 693 06 90
MERKEZ FAX : (0216) 693 15 50